INSPECTION REPORT

Partial XXX Complete Exploration
Inspection Date: 07/02/2003 / Time: 08:30 AM to 2:00 PM
Date of Last Inspection: 06/18/2003

Mine Name: Castle Gate M	<u>line</u> County	: <u>Carbon</u>	Permit Number: <u>C/007/004</u>			
Permittee and/or Operator's Name: Castle Gate Holding Company						
Business Address: P.O. Box 30, Helper, Utah 84526						
Company Official(s): John	ny Pappas					
State Official(s): Joe Helfrich Federal Official(s): None						
Weather Conditions: 75, sunny						
Type of Mining Activity: Underground XXX Surface Prep Plant Other						
Existing Acreage: Permitted 7619 Disturbed 63 Regraded Seeded						
Status: Active Reclamation	ı XXX					

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For <u>partial inspections</u> check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[X]		[X]	
2.	SIGNS AND MARKERS	[X]	\Box	[X]	ĹÌ
3.	TOPSOIL	ĹĹ	Ĺĺ	Ĺĺ	Ĺĺ
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS	[X]	\Box	[X]	\Box
b.	SEDIMENT PONDS AND IMPOUNDMENTS		ΞĪ		百
c.	OTHER SEDIMENT CONTROL MEASURES	ĪĪ	ĪĪ	<u> </u>	Ī
d.	WATER MONITORING	$\overline{[X]}$	亘	\Box	口
e.	EFFLUENT LIMITATIONS		ΞĪ		百
5.	EXPLOSIVES	Ī	[X]		口
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	$\overline{\Box}$	[X] [X] []		ΞĪ
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	Ĺĺ	ĹĬ	Ĺĺ	Ĺĺ
8.	NONCOAL WASTE	Ĺĺ	Ĺĺ	ĹĬ	Ĺĺ
9.	PROTECTION OF FISH, WILDLIFE AND RELATED	\Box			
	ENVIRONMENTAL ISSUES	\Box		\Box	
10.	SLIDES AND OTHER DAMAGE	\Box		\Box	
11.	CONTEMPORANEOUS RECLAMATION	\Box	\Box	\Box	
12.	BACKFILLING AND GRADING	\Box		\Box	
13.	REVEGETATION	[X]		[X]	
14.	SUBSIDENCE CONTROL	\Box	\Box	\Box	
15.	CESSATION OF OPERATIONS	\Box	[X]	\Box	
16.	ROADS:	\Box			
a.	CONSTRUCTION/MAINTENANCE/SURFACING	\Box	\Box	\Box	
b.	DRAINAGE CONTROLS	\Box	\Box	\Box	
17.	OTHER TRANSPORTATION FACILITIES	\Box	[X]	\Box	
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	\Box	\Box	\Box	
19.	AVS CHECK (4 th Quarter- April, May, June)			\Box	
20.	AIR QUALITY PERMIT	\Box			
21	RONDING & INSURCE	r 1	ГΊ	ГТ	Γī

INSPECTION REPORT

(Continuation Sheet)

PERM	TT NUMBER: <u>C/007/004</u>	DATE OF INSPECTION: <u>07/02/2003</u>
	(COMMENTS ARE NUMBERED TO COR	RRESPOND WITH TOPICS LISTED ABOVE)
1.	PERMITS, CHANGE, TRANSFER, REN	EWAL, SALE
	The purpose of this visit was to conduct a pa	rtial inspection of the #1 Adit.
2.	SIGNS AND MARKERS	
	The sign containing the required information	was posted at the access point to the #1 Adit.
4A.	HYDROLOGIC BALANCE: DIVERSIO	NS
		I repair and were functioning properly at the Adit. ne flow extends about half way across the reclaimed
13.	REVEGETATION	
	The Adit: Vegetation has emerged through 6"-10" of new growth.	the straw mulch in the roughened areas and is showing
Inspec	tor's Signature: Joseph C. Helfrich #1	Date July 7, 2003
Note:	This inspection report does not constitute an affidavit of com	pliance with the regulatory program of the Division of Oil, Gas & Mining.
cc:	James Fulton, OSM Johnny Pappas, Castle Gate Holding, via email	
O:\00700	Price Field office 04.CG\Compliance\2003\P_0702.doc	